## Amendments to the Specification

Please replace paragraph [0053] with the following rewritten paragraph:

[0053] Above the first lip 40, the insert 41-31 has a second annular lip 41 bearing in leaktight manner against the inside surface 15a while the moving assembly is in its rest position, as shown in Figure 1.

Please replace paragraph [0099] with the following rewritten paragraph:

[0099] Continued upward movement of the moving assembly 62 relative to the stationary portion 61 causes substance to be sucked into the pump chamber, the first lip 80 pressing against the pump body 65-above below the opening 88, as shown in Fig. 5.